

On this Survey I found it necessary to Establish the SE^{2nd} SW Corner Sec 1 and the SW Corner Sec 2 T⁹ R 31
Beginning at SW Corner Sec 12 (Which was found by running East from the SW Cor Sec 11 which is witnessed by pine) (Note: ^{this} Corner at SW Cor Sec 12 was unknown to Land owners of vicinity - so it had been undisturbed. It was supposed by the Land Owners that this Corner was 80 rods on road East of its true position and as much north. The location of this Corner in its true position, produce a great change in their lines fences and Houses.

From this Corner ran north on Random

1/4 Cor missing

NW Cor Sec 12 missing

1/4 Cor "

The NW Cor Sec 1 falling West 48 lks

Proceed to the 1/4 Corner between Sec 7th & 18th Town 9 Range 32 Which is witnessed by two Pines I run West on Random

The 1/4 Cor between Sec 3rd & 10th T⁹ R 31 falling South 89 links

I then went over these lines and corrected the temporary Corners placed on these random lines in proportion to the measure as given in Cor field notes and marked and established the Corners along these lines

Proceeded to divide Section 1 Town 9 R 31E

by running straight lines from opposite 1/4 corners and at their intersection let the center also divided the SW 1/4 of this Sec in like manner from opposite 1/4 Corners

The weather being Cold Winterfast approaching Ground frozen pressed for time and it being rumored that one of the Land owners (Who lost House Garden Orchard and Spring by this survey) would call for a review. I did not set the Corners ^{in the ground} in witness, leaving this Survey in this particular incomplete until such future time when it could be finished. The corners were all placed at correct point however and all had a mound of Stones around them and the corners were marked

Corners Established are shown by crosses on the Plat

Also in order to Establish the North West Cor Sec 11 I measured North from South W Cor Sec 11 The 1/4 Cor between 2nd & 3rd falling E 37 links

Latitude 44° 46' Declination - 20° 48' Variation of Needle very changeable not to be relied Ranging from 10° - 28° E. In Cor field notes notice the same trouble. Weather was cloudy most all the time, I ran this Survey entirely by back-sight fore-sight, taking for my Standard the South line of Sec 2

Also in regard to the 1/6 corner East of SW cor Sec 11. It falling on gravel bar close to River Edge, where it would not be practical to place it. I erected a Mound of Rocks and placed a marked Rock South of this point. 128 lks

Surveyed Nov 23-29 1908

Dec 10 1908 Michael Spears County Surveyor