

Application for establishment of Lines for Corners of 1/4 NE 1/4 Sec 10 - The SW 1/4 SE 1/4 Sec 10 Township 14 S Range 31 E By Ed Cain

Parties Notified Geo Sollinger Sen. Geo Sollinger Jun. Oliver Sollinger Henry Rich. Will Morgan Edward Cain Mrs Sarah Goodman John Adams John Tracy appeared on scene. Mr E H Goss was notified

May 10 1909 I proceeded to the SW Corner Sec 10 Twp 14 Range 31 E at one o'clock James Kane W A Smith C A Pierce sworn as Magistrate & Chain carriers Ed Cain appointed Assessor. Being informed that all of the original Corners of Sec 10 were missing except the SW I began at SW Corner which is in good condition with the Witness Trees as described in US Field notes

East-

20 set Twp 1/16
40 27 The 1/4 Corner not plainly marked falling North 22 links I marked and established corner however in good condition
Thence from the 1/4 Corner Ran East
20 set Twp 1/16
40 Section Corner used as fence weight on Sollinger fence and also all witness trees as described in US Field notes destroyed Ran East
80 1/4 Corner missing Ran East
104 18 Canyon Creek
120 Sec Corner Missing comes on side of steep hill in a field of loose rocks cut by stock trails
I then followed Sec 10's instructions to use Natural objects described in US Field Notes as a means of locating the SE Corner Sec 10. The difference between our measure and Government measure from SW Cor Sec 10 to Canyon Creek being .85 lks I proceeded to temp SE Cor Sec 10 and corrected it 43 links East

Now proceed to Corner 14-15-22-23 which is in good condition with

Three of the Witness Trees remaining Ran North

40 1/4 Cor miss
83 40 The Temp corrected E-W. SE Cor Sec 10
120 1/4 Cor miss
160 NE Cor Sec 10 Miss
200 W 1/4 Cor Sec 2 Miss
226 42 The NW Cor Sec 2. Found this Corner being used as fence weight on Geo Sollinger fence Mr Ed Cain testified to seeing this Corner North of its present position (ie fence weights) about 35 lks a pile of rocks were there with a place in centre as if a Corner had been removed. I placed it there and corroborated Ed Cain's testimony by taking observations on Corners 3 miles East on standard parallel with which I was acquainted and finally ran East-

43 38 The Cor Sec 34-35 Twp 13 S R 31 E without any falling
Then to corroborate with the parallel corner West I ran West from the Clearing Corner Sec 2-3 Twp 14 R 31 We proceeded West measuring carefully and found no corner either Clearing or Standard along the line until we came to Standard Corner Sec 36 Twp 13 R 30. My opinion is that we would not have found this had it not been partially concealed by brush and blazed marks down underneath falling North 27 links
Mr Cain's testimony having been thus satisfactory corroborated I proceeded to Temp NE Cor Sec 10 and corrected it North 728 lks (its proper amount of the proportion of difference) Have to say that finding there was a difference of 10 chs between our measure and Gov measure from Corner 14-15-22-23 and Clearing Cor Sec 2-3 I remeasured to measure and found no mistake

Now NE Corner Sec 10 Ran West

40 1/4 Cor miss
80 NW Cor Sec 10 missing
120 1/4 Cor missing
160 NW Cor Sec 9 missing
200 40 The South 1/4 Cor Sec 5 fall North 120 lks

Michael Stearns Jan 2-1909