

SW Corner Section 1

Found marked stone 16x8x6 in mound.

We scribed:

12" Juniper S 61° East 35.0 ft.	"S 12 BT"
9" Pine S 35° West 16.6 ft.	"S 11 BT"
16" Pine N 32° East 18.0 ft.	"S 1 BT"

No trees in NW Quadrant.

East $\frac{1}{4}$ Section 1

Found original 20" Tam. marked " $\frac{1}{4}$ " for corner per original notes.
Now rotting windfall.

We set stone 12x8x7, " $\frac{1}{4}$ " on north, in mound.

Scribed new BT's:

12" B. Pine N 82° E 16.2 ft.	$\frac{1}{4}$ S BT
10" Fir S 32° E 22.3 ft.	

This corner is on gentle west slope about 70 ft. more or less east of shallow draw north.

Southeast corner Section 1

Found marked original stone 18x8x8 in mound and scribed new BT's.

7" Juniper S 35° West 41.7 ft.	"S 12 BT"
28" Leaning pine S 72° East 28.2 ft.	"S 7 BT"

No other trees within reason. Corner is near east edge of flattish gentle east slope.

It should be noted for record purposes that the SE corner of Section 6, Township 12 south, Range 29 East is probably ok and in its original location. However, the bearings and distances to the original scribed BT's do not check well. We find the following:

Stone 12 x 8 x 8
 16" Juniper, N 20° E 51.2 ft. now 30" Juniper, N 19° E 56.5 ft.
 30" Pine S 46° East 10.0 ft., now 38" Pine S 50° E 70.4 ft.
 35" Pine, S 25° W 13.2 ft., now 38" Pine S 24° W 19.5 ft.
 12" Pine, N 65° W 64.3 ft., now 27" Pine N 65° W 66.0 ft.

All of these trees had been chopped out to original scribes many years ago and all are standing and in good condition.

There is a location tag on ridgetop road south of this corner.

These corners have all been witnessed by Mr. Hamilton and his chainman, as well as Larry Baker, Lebanon, Oregon and myself. (Except that I personally, did not get to NW corner Section 1.)

Very Truly yours,

Howard E. Taylor
 Howard E. Taylor, RPE 2891