

CORNER RESTORATION


N.E. Cor.
CORNER Sec. 34 TWP 15 S. RANGE 32 E.

ORIGINAL SURVEY BY:

CONTRACT NUMBER:

CONTRACT DATE:

RESURVEY: Geo. Rigby
Group No. 215
April 19, 1939



ORIGINAL DESCRIPTION:

80.03 RESURVEY: GEO. RIGBY - Orig. cor. of Secs. 26, 27, 34 and 35, which is a fragment of basalt stone still in the ground where the orig. stone has been smashed by falling tree.

Set Iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground for cor. of Secs. 27 and 34 only, with brass cap mkd.

From which: A pine 10 ins. diam., brs. S. 26° 00' W., 90 lks dist. mkd	T15S	S26
T15SR32E S34 BT (New BT)	S27	
A pine 30 ins. diam., brs. N. 30° 00' W., 152 lks. dist. mkd	S34	
T15SR32E S27 BT (Old BT)	R32E	1939

RESTORATION BY, STAMP AND DATE:

R. D. BAGETT
W. GENTIS



FEB. 1976

GRANT COUNTY SURVEYOR

EVIDENCE FOUND:

Found 1939 GLO Brass Cap firmly set as shown below

From which:

A 40" pine brs. N. 30° W. 152 lks. dist. with partially healed blaze.

An 18" pine brs. S. 26° W. 90 lks. dist. with partially healed blaze.


DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Since I found this corner and the BTs in excellent shape I did nothing on the ground to further perpetuate the position of this corner. I am filing this remonumentation sheet as an update on the condition of the corner.

MONUMENT MARKED

See Map of Survey No. 398



RECEIVED AND
FILED

NOV 29 1976

JOHN LIVEIRA, County Clerk

By Parlene L. Loman Deputy