

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by S. W. Lackland, US Deputy Surveyor, during the original survey Joint Contract No. 357 dated July, 1880.

Set post for 1/4 sec cor with pits and mound as per instruction.

DIAGRAM

T16S R30E

1/4 $\frac{S28}{S33}$

1986
PLS 699

Description of corner evidence found:

The corner falls in a meadow hay field. No evidence of the original corner was found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 3 1/4" aluminum cap, marked as shown in the diagram, 30" in the ground to not interfere with haying operations, at single proportionate measurements from adjacent found corners.

No new bearing trees set because no trees are within the allowable limits.

No. 6x30" Rebar with 2" aluminum cap Reference Monument bears N89° 13' 50"E, 94.0 feet on the property line and in the right-of-way fence marked RM ← 94.0' 1986 PLS 699 with steel fence post 1' E

No. 6x30" Rebar with 2" aluminum cap Reference Monument bears South, 44.2 feet on the property line and in the right-of-way fence marked RM 44.2' ↑ 1986 PLS 699 with steel fence post 1' S

Set steel fence posts 45 feet S and 95 feet E of the corner on the National Forest property lines. Attached Forest Boundary signs to each post and an Attention sign to the S post.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on June 11, 1986, I re-established the corner as herein described.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Leland L. Myers

OREGON
JULY 9, 1965
LELAND LEE MYERS
699

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 30 DAY OF Sept, 1986

Robert D. Bayetta
Grant County Surveyor