

OREGON CORNER RESTORATION RECORD

SECTION 6 TOWNSHIP 10 S RANGE 26 E

CENTER 1/4 SECTION 6

GRANT COUNTY

DATE 2/4/91

CORNER DESIGNATION

TYPE OF REPORT

COUNTY SURVEYOR'S RECEIPT STAMP

CENTER 1/4

CONDITION ONLY

INDEX FILE NO.

SECTION 6

NOT FOUND

RENEWED

UNRECORDED

SURVEYED IN

REFERENCED OUT

ALPHA/NUMERIC

CORNER NUMBER C-03

HISTORY OF ORIGINAL CORNER AND / OR PREVIOUS RENEWALS:

None

DESCRIPTION OF CORNER EVIDENCE FOUND:

None

RECEIVED AND
FILED

AUG 15 1991

SEE MAP OF SURVEY NO. 1162


OFFICE OF COUNTY SURVEYOR
Attest: *[Signature]*

MONUMENT DETAIL

SKETCH

LOCATION / COMMENTS:

MAG. DECL. 20° E



U.Pole

Corner: 14" J
5" J
12" J

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED:

Set 5/8" x 30" Iron rod with plastic cap marked "LS 1020" from which:

A 12" Juniper Brs. S 15° E 56.8'

A 5" Juniper Brs. S 47° E 44.7'


A 14" Juniper Brs. N 24° E 48.8'

A Utility Pole Brs. N 2° W 103.7'

Accessories identified by having a brass disc marked "LS 1020" attached thereto.

FIRM / AGENCY NAME: George Colvin
Land Surveyor
ADDRESS: 22947 Branding Iron Cr.
Bend, OR 97701

SURVEYOR'S
SEAL



C-3