

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. G-17

History of original corner establishment:

Corner was originally established by Herman D. Gradon under GLO contract No. 416 during October, 1881. Surveyors General's notes state: "Set a granite stone 15x8x6 ins. 10 ins. in the ground for 1/4 sec. cor. marked 1/4S on W face: from which, A fir 15 ins. diam. bears N55°E, 42 lks. dist. marked 1/4S BT. A tamarac 18 ins. diam. bears S70°W, 43 lks. dist. marked 1/4S BT."

DIAGRAM

W.C. 10.0 ft. No.
T10S R35E
1/4
S10 + S11
OR PLS 1051
1980

Description of corner evidence found:

Corner falls in ditch. Measured S50°W, 27.7 ft. from 30" live fir scribed 1/4S. A 30" cut tamarac with some scribing is on the west bank of ditch. No stump.

Description of monument and accessories established to perpetuate the original location of this corner:

W.C. 10.0 ft. No.
T10S R35E
1/4
S10 + S11
OR PLS 1051
1980

As corner cannot be set in ditch measured North 10.0 ft to top of bank and set 2 1/2" X 30" galvanized pipe and brass cap marked; Set pipe 24" in the ground and mound of stone around to cap. From true corner position: An 11" lodgepole pine bears N72°W, 63.7 ft, scribed 1/4S10 BT. Painted blazes red and 6" red band around. Placed 54-3, 54-4 and brass washers stamped PLS 1051 on BTs, Placed 54-4 on steel fence post 5' north of W.C.

I hereby certify that the above corner monument was reestablished as herein described,

Witnesses: Daniel Rowland
Doug Moser

October 22, 1980

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Barry B. Barbour
OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

Office of...County Surveyor...County of...Grant...
State of...Oregon...I hereby certify that the within instrument was filed in this office
for record on the...20th day of...January...1981.
Robert D. Sargent by _____
(COUNTY OFFICIAL) (DEPUTY)