

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. X-9

History of original corner establishment:

Corner originally established by
W.H. Byars, in 1873, under General
Land Office Contract No. 197.
Surveyor Generals Notes, State:
Set Basalt Stone 14x10x8 for
1/4 Sec. Cor.

DIAGRAM

T11S R30E
1/4
|
S32. S33
|
1985
PLS 848

Description of corner evidence found:

No Evidence found, Corner falls in a meadow, it
looks like a house was just north of the corner area
at one time.

No accessories originally established.

Corner has been lost to building and farming activity
over the years.

Corner position is determined by proportionate measure
from Corners found 1/2 mi. North & South.

**Description of monument and accessories | established to perpetuate the
original location of this corner:**

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown
on the **DIAGRAM**, SET 20" in the ground and placed a ring of stone & earth
the pipe.

From Which:

A Juniper 16" dia., Bears N19°51'W., 123.4 ft., scribed: 1/4 S32 BT

A Juniper 12" dia., Bears N33°13'E., 113.9 ft., scribed: 1/4 S33 BT

Measurements to trees taken with a theodolite and electronic equipment
with angle turned from survey control.

Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing
Tree Sign above blaze, and warning sign on back of each tree. Painted
a 6" red band at breast ht. around each tree. Set steel fence post with
warning Sign, North 2 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: Oct. 3, 1985
Refer to Map of Survey No. 904

Office of... *Surveyor* County of... *Grant*
State of... *Oregon* I hereby certify that the within instrument was filed in this office
for record on the... *29* day of... *Dec* 19... *85*
..... *Robert D. Buzza* by
(COUNTY OFFICIAL) (DEPUTY)