

TOWNSHIP 12 SOUTH, RANGE 28 EAST

$\frac{1}{4}$ 17/16

Found marked stone.

Orig. 40" pine N 20 East 15.2 ft. now 48" bearing N 25° E 15.2 ft., scribed and in good condition.

L-9

Orig. 61" Pine N 60° W 20 ft. was actually 6" Pine and is now 24" pine N 60 W 20 ft. Scribed and in good condition.

There is a home-made brass cap supposedly for this corner in fence about 250 feet SE and it is obviously haywire.

$\frac{8}{9}$

$\frac{17}{16}$ Found marked stone

Orig. 5" Pine N 20 East 36 ft. now windfall with scribe.

Orig. 22" Pine S 35 East 10.6 ft. now 23". Good condition.

Orig. 6" mahogany S 80 W 16.5 ft. now dead with scribe.

Orig. 14" Pine N 20 W 21.8 ft. Now 24". Good Condition.

J-9

I scribed:

8" Fir N 54 E 21.4 ft. "S9 BT"

5" Fir S 84 W 24.2 ft. "S17 BT"

$\frac{1}{4}$ 17/20

Found marked stone (notes 16x12x4, but measures 19x14x4).

Orig. 25" Pine N 80 E 6.6 ft. was actually a fir bearing N 30 E 6.6 ft. with bark scribe. This is now rotting windfall.

Orig. 36" Pine S 50 W 9.0 ft. was actually a fir and is now rotting stub, bearing and distance ok.

There is an orig. line blaze on big Pine snag 100 ft. more or less west of above corner. There is also a home made brass cap supposedly representing this corner about 354 ft. more or less east of and 30 ft. more or less north of this orig. corner. It is obviously in error.

N-7

I scribed new BT's as follows:

5" Fir N 72 East One foot "1/4 S BT"

10" Fir N 48 West 12 ft. "1/4 S BT"

$\frac{1}{4}$ 8/17

Found Orig. marked stone.

Orig. 20" Pine N 50 E 8 ft. now 24" good condition.

Orig. 18" Pine S 5 E 17.8 ft. Now 23". Good Condition.

Put tag on second BT above.

J-7