

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. J-9

History of original corner establishment:

In Sept., 1881 under Contract No. 415, Samuel W. Lackland marked a Tamarack 24 ins. dia. for Cor. to Secs. 8, 9, 16 & 17 with T.12S, S9 on N.E., R30E, S16 on S.E., T.12S, S17 on S.W. and S8 on N.W. faces with 4 notches on S. and 4 notches on E. edges from which:

A Fir 12 ins. dia. bears N37°E, 21 lks dist. marked T.12S, R.30E, S9 BT.

A Fir 12 ins. dia. bears N41°W, 24 lks. dist. marked T.12S, R.30E, S8 BT.

A Fir 10 ins. dia. bears S16°W, 27 lks. dist. marked T.12S, R.30E, S17 BT

A Fir 20 ins. dia. bears S22°E, 17 lks. dist. marked T.12S, R.30E, S16 BT.

DIAGRAM

T12S R30E	
S8	S9
S17	S16

Description of corner evidence found:

At corner position found rotted remains of original corner Tamarack with piece of tree with scribing "OE S16". Found a 30" White Fir bearing N32°E, 14.5 ft, with healed over blaze painted red. BT 54-3 sign and 54-4 signs are attached. 6" band painted red. Found a White Fir 30" dia. bearing S25°E, 13.5 ft, with partially healed over blaze, visible scribing "OE". Found a White Fir 15" dia. bearing S10°W, 19.5 ft, with healed over blaze. Found remains of N.W. BT with visible scribing "T.12S, R.30E, S8" BT. Indentation where tree was bears N34°W, 17.0 ft. All found original BT's have 54-3 signs by W.J.K. 7/24/77 and 54-4 signs attached. Blazes and 6" band are painted around BT's. The original BT's seem to have been measured from the edge of the original corner tree because record distances from original BT's outline the remains of the found rotted corner tree.

Description of monument and accessories I established to perpetuate the original location of this corner:

At center of the rotted remains original corner tree set 2½"x30" aluminum pipe with cap stamped:

Set pipe 24" in ground.

Used all old BT's and blazed new BT N.W. a White Fir 10" dia. bears N32°W, 59.6 ft, scribed T.12S, R.30E, S8 BT.

Attached 54-3 & 54-4 signs to new BT. Attached brass washer stamped LS 1294 to foot blaze of new BT. Painted blazes and 6" band around new BT red. Attached 54-4 sign to metal post 6' South of corner.

T12S R30E	
S8	S9
S17	S16

1981
OR PLS 1294

I hereby certify the above corner monument was re-established as herein described on May 5, 1981.

Witnesses: R. Orton
G. Orton
A. Hanley



Office of..... County Surveyor..... County of..... Grant
State of..... Oregon....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....
Robert D. Baggett by.....
(COUNTY OFFICIAL) (DEPUTY)