

TOWNSHIP 12 SOUTH, RANGE 30 EAST

page 2

18/19
19/20 (cont.)

I scribed new BT's:

48" Fir	N 78 E	28.5 ft.	"S17 BT"
28" Fir	S 13 W	10.8 ft.	"S19 BT"

$\frac{1}{4}$ 28/33

COR Re-mon
PLS 848 1983

Found Orig. stone.

Orig. 30" pine S 78 W 19.8 ft. was actually S 62 W and is now windfall with scribe.

Orig. 18" pine S 61 E 19.1 ft. now about 24" with scribe.

Put tag on ~~Forest~~ boundary sign on Warm Springs road west of here.

$\frac{1}{4}$ 31/32

COR Re-mon
PLS 848 1983

Found orig. stone downhill below both BT's and reset it at intersection of note distances.

Orig. 16" pine S 5 W 2.0 ft. is now stump with old face burned off and bearing was actually S 35 W.

Orig. 28" pine N 60 E 12.0 ft. is now stump. We cut it out to orig. scribe and put tag on it. Actual bearing was N 80 E.

Scribed:

10" Pine	N 1 W	71.0 ft.	" $\frac{1}{4}$ S 31 CS BT"
10" Pine	N E	63.0 ft.	" $\frac{1}{4}$ S 32 CS BT"

(notes incomplete on bearing)

Put location tag on north edge old logging road about 250 ft. north of this corner which falls on east bank of east fork of Damon Creek.

24/19
25/30

COR Re-mon
PLS 848 1983

On West boundary T 12 S, R 30 E W.M.

Found Orig. Stone

Orig. 16" Pine N 20 W 33 ft. now windfall with scribe.

Orig. 12" Pine S 36 E 19.8 ft. now 16" Good Condition.

Orig. 12" Pine S 72 W 52.8 ft., Now 24" OK with tag.

Orig. 20" Fir N 81 East 45.5 ft. Now 20" rotted windfall with scribe.

I scribed new BT's as follows:

10" Fir	N 12 W	45.0 ft.	"S24 BT"
8" Fir	N 5 E	31.4 ft.	"S 19 BT"