


History of original corner establishment:
 Corner not set in original survey.

I established this $\frac{1}{4}$ corner at the intersection of lines from opposite corresponding $\frac{1}{4}$ corners of the section.



No record of subsequent monumentation found in County records.
 Description of corner evidence found:

None

See map of survey dated September, 1980.

Description of monument and accessories I established to perpetuate the original location of this corner:

At intersection I set $2\frac{1}{2}$ " x 30" aluminum monument marked as shown 27" in ground from which;

NEW BTs


A 10" p pine bears N 45° E, 6.8 ft marked $\frac{1}{4}$ S19 BT

A 14" p pine bears N 38° W, 20.6 ft marked $\frac{1}{4}$ S19 BT

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

Robert D. Boyer

OREGON
 JULY 10, 1964
 DUANE I. GRIFFITH
 644



Brass washer nailed to BT blaze.
 Used steel tape and magnetic compass
 with 15° East declination.
 Measured to center of new B.T.s

Office of *Surveyor* County of *Grant*
 State of *Oregon*, I hereby certify that the within instrument was filed in this office
 for record on the *31* day of *Oct*, 19*80*
Robert D. Boyer by _____
 (COUNTY OFFICIAL) (DEPUTY)