


History of original corner establishment:
Corner not set in original survey.

I established this 1/16 corner at midpoint and on the line between the E 1/4 corner and the center 1/4 corner of the section.



No record of subsequent monumentation found in County records.
Description of corner evidence found:

None

See map of survey dated September, 1980.

Description of monument and accessories I established to perpetuate the original location of this corner:


At intersection I set 2 1/2" x 30" aluminum monument marked as shown 19" in ground from which;

NEW BTs

A 26" p pine bears N 3° E, 53.8 ft marked CE 1/16 S19 BT

A. 10" juniper bears S 55° W, 3.2 ft marked CE 1/16 S19 BT

Raised mound of stone 4 ft base to top of monument.



Brass washer nailed to BT blaze.
Used steel tape and magnetic compass with 15° East declination.
Measured to center of new B.T.s

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 31 day of Oct, 1980
Robert D. Beyer by _____
(COUNTY OFFICIAL) (DEPUTY)