


CORNER RESTORATION

SE1/16 Cor.
CORNER Sec. 16 TWP 12 S., RANGE 35 E., W.M.
ORIGINAL SURVEY BY: BAMFORD ROBB
CONTRACT NUMBER: 383
CONTRACT DATE: March 26, 1881



ORIGINAL DESCRIPTION:

Corner not previously established of record.
I established the SE 1/16 corner at the intersection of lines from opposite corresponding 1/16 corners of the SE 1/4 of Sec. 16.

RECEIVED AND
FILED

RESTORATION BY, STAMP AND DATE:

R. D. Bagett
F. Jackson
K. Leckenby

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett
OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

JUL 2 1979
John Liveira
JOHN LIVEIRA, County Clerk
By..... Deputy

June 9, 1979 Grant County Surveyor.

EVIDENCE FOUND:

See Map of Survey No. 570.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:
Show how trees are scribed and basis of bearings, including compass var.

At the corner point: Set 5/8"x30" iron pin in a mound of stone, from which I scribe NEW BEARING TREES:
A 48" tamarack bears S. 56° W., 95.3 ft. mkd. SE1/16S16CSBT.
A 4" lodgepole bears N. 50° W., 25.8 ft. mkd. XCSBT.
I used true bearings and steel tape, measuring to the face of the blaze on the bearing tree.

MONUMENT MARKED

