

CORNER RESTORATION

CORNER: NE SEC. 22, TWP. 13 S., RANGE 31 E., W.M.

ORIGINAL SURVEY BY: John B. David


CONTRACT NUMBER: 131

CONTRACT DATE: June 8, 1869

SUBSEQUENT SURVEYS:

- ▶ Remonumented by Robert Bagett, County Surveyor, Sept. 15, 1975.
- ▶ New corner accessories established by Robert Bagett, County Surveyor in 1994.

See Corner Restoration Records.



ORIGINAL DESCRIPTION: Set Stone 19"x12"x8" for cor to secs. 14, 15, 22, & 23.

- ▶ Bagett found the original stone in 1975. His record states:
Set 1½"x30" iron pipe 24" in the ground with brass cap as shown.
- ▶ Bagett revisited this corner in 1994 and established new accessories. His record states:
A 5/8"x30" iron pin, bears N45°E, 25.00 ft., with attached alum. cap marked GRANT COUNTY SURVEYOR RP 1 1994 OPLS 598.
A 5/8"x30" iron pin, bears S45°E, 25.00 ft., with attached alum. cap marked GRANT COUNTY SURVEYOR RP 2 1994 OPLS 598.
A 5/8"x30" iron pin, bears S45°W, 25.00 ft., with attached alum. cap marked GRANT COUNTY SURVEYOR RP 3 1994 OPLS 598.
A 5/8"x30" iron pin, bears N45°W, 25.00 ft., with attached alum. cap marked GRANT COUNTY SURVEYOR RP 4 1994 OPLS 598.


RESTORATION BY, STAMP AND DATE:

J.L. Hatfield, PLS

RECEIVED AND
FILED

April 16, 2010
OFFICE OF COUNTY SURVEYOR


ATTEST:



March 18, 2010

Grant County Surveyor (Deputy)

EVIDENCE FOUND AND NEW ACCESSORIES: Found a 1½" iron pipe with attached 2½" brass cap attached, marked as shown below, set in a mound of stone. The monument is in good condition. I also found all four reference points in place and in good condition.



STATE PLANE COORDINATES (3601 OR N) Reference Datum: NAD83

Northing: 282,959.03 ft.

Easting: 8,604,085.49 ft.

Ellip. Ht: 3,556.42 ft.