

RE-ESTABLISHMENT OF $\frac{1}{4}$ CORNER BETWEEN
SECTIONS 20 & 29, T.13S., R.31E. W.M.

I did not find the original monument nor any subsequently set monument for this corner. Its position, however, is not lost. Several land title ties have been made to this corner said ties appearing in deed descriptions.

Deeds, Book 50 Page 111 calls for the point of beginning to be " 209.6 feet South and 112.0 feet East from the $\frac{1}{4}$ corner common to sections 20 and 29, T.13S., R.31E., W.M."

Other properties adjoining this tract and property nearby harmoniously relate to this position.

Although I found no survey monuments on the tract described in Book 50 Page 111 of Deeds, the fencelines and the location of the highway are in harmony with the description.

I therefore accept the location of this tract as the best available evidence in positioning the North $\frac{1}{4}$ corner of Section 29, and place the $\frac{1}{4}$ corner at record Northing and Westing from the NW corner of the above described tract.

See attached remonumentation sheet for details of monument set and accessories. See also Map of Survey No. 304.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Baggett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

Grant County Surveyor

May 21, 1973