


CORNER RESTORATION

CORNER: N1/4 COR. SEC. 34, TWP. 13 S., RANGE 31 E., W.M.

ORIGINAL SURVEY BY: John B. David

CONTRACT NUMBER: 131

CONTRACT DATE: June 8, 1869



Subsequent surveys:

- ▶ 1973, remonumented by Robert D. Bagett, Grant County Surveyor
- ▶ 1995, new accessories by Robert D. Bagett, Grant County Surveyor
- ▶ 2003, new accessories by Robert, D. Bagett, Grant County Surveyor

ORIGINAL DESCRIPTION: Set stone 14x12x10 for 1/4 corner

- ▶ See Corner Restoration Records for information on surveys in 1973, 1995 and 2003.

RESTORATION BY, STAMP AND DATE:

Michael C. Springer, PLS

**RECEIVED AND
FILED**

December 11, 2009

OFFICE OF COUNTY SURVEYOR

ATTEST:

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Michael C. Springer
OREGON
JULY 9, 2002
MICHAEL C. SPRINGER
#70918

EXPIRES: 6/30/2010

December 1, 2009

Grant County Surveyor

EVIDENCE FOUND: Found Grant County Surveyor brass cap marked, as shown below, in a mound of stone. All record reference points are in good condition. Corner is in an East-West fence on the North boundary of the Grant County Regional Airport.

STATE PLANE COORDINATES: (3601 OR N) Reference Datum: NAD83

Northing: 272,282.13 ft.

Easting: 8,601,684.69 ft.

Ellip Ht: 3,586.6 ft.

