


CORNER RESTORATION

S. $1/4$ Cor.
CORNER Sec. 34 TWP 13 S., RANGE 31 E., W.M.

ORIGINAL SURVEY BY: John B. David

CONTRACT NUMBER: 131

CONTRACT DATE: June 8, 1869



ORIGINAL DESCRIPTION:

S $89^{\circ} 57' W$ on true line between Secs. 33 and 34 .

Var. 23° East.

10.00 Road bears NE., SW.

40.00 Set stone $17 \times 8 \times 7$ for $1/4$ Sec. Corner.

RECEIVED AND
FILED

JAN 15 1974

JOHN LWEIRA, County Clerk

By Betty Lowmyer Deputy

RESTORATION BY, STAMP AND DATE:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Baggett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

December 6, 1973

Grant County Surveyor

EVIDENCE FOUND: SEE MAP OF SURVEY NO. 324.

The original $1/4$ stone was not found.

The position of the $1/4$ corner was established by means of single proportionate measure between the accepted section corners, the SE. corner Sec 34 , $1/2$ mile East, and the SW. corner Sec. 33 , $1/2$ miles West.

This corner falls about 30 feet North of an E-W fence.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At point for $1/4$ corner: Set a $1\frac{1}{2} \times 30$ " iron pipe $2\frac{1}{4}$ inches in the ground with a brass cap marked as shown: **MONUMENT MARKED**

Raised a mound of stone to the top of the pipe.

No suitable bearing trees available.

Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820

