

CORNER RESTORATION

CORNER: W1/4 Sec 31 TWP 13S. RANGE 32E.


ORIGINAL SURVEY BY: John B. David

CONTRACT NUMBER: 131

CONTRACT DATE: June 8, 1869

Subsequently remonumented by the Bureau of
Land Management Aug-Sept 1971.

See BLM field notes of Record Map of
Survey No. 286.



ORIGINAL DESCRIPTION: Set Stone 16x12x6 for 1/4 Sec. corner.

The BLM found the original stone in 1971. Their record states:

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground,
with brass cap mkd. (marks shown below).

RESTORATION BY, STAMP AND DATE:



R.D. Bagett
G.J. Russell
S.D. Follweiler

RECEIVED AND
FILED

MAR 2, 1995
OFFICE OF COUNTY SURVEYOR

Robert D. Bagett

ATTEST: *Jeremy Russell*



Renewal Date 12/31/95

February 24, 1995

Grant County Surveyor

EVIDENCE FOUND: Found a $2\frac{1}{2}$ " galvanized iron pipe with attached 3" brass
cap marked as shown below, set in a mound of stone.

Corner is 10' east of fence running North and South.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:
Show how trees are scribed and basis of bearings, including compass var.

The monument set in 1971 is in good condition.

MONUMENT MARKED

From which: I SET NEW REFERENCE POINTS:

A 5/8"x30" iron pin, bears N27°E, 25.00 ft., with
attached alum. cap marked GRANT COUNTY SURVEYOR RP 1
1995 OPLS 598.

A 5/8"x30" iron pin, bears S20°E, 20.00 ft., with
attached alum. cap marked GRANT COUNTY SURVEYOR RP 2
1995 OPLS 598.

A 5/8"x30" iron pin, bears S27°W, 20.00 ft., with
attached alum. cap marked GRANT COUNTY SURVEYOR RP 3
1995 OPLS 598.

A 5/8"x30" iron pin, bears N20°W, 20.00 ft., with
attached alum. cap marked GRANT COUNTY SURVEYOR RP 4
1995 OPLS 598.

BUREAU OF LAND
MANAGEMENT
T13S
R31E R32E

$\frac{1}{4}$
S36 | S31
1971

Repaired mound of stone 2 ft. base to top of cap. Used mag. compass with
20°E var. and a steel tape.