

wnship 15 south, Range 35 East

South $\frac{1}{4}$ Corner, Section 31

Found original marked stone 16x10x6 in mound, $\frac{1}{4}$ on top.

Original 24" Pine recorded as S 34 E 18 ft. is now windfall with exterior gone.

The bearing actually was S 84 E and distance ok.

I scribed new BT's as follows:

9" Juniper S 87 E 36.7 ft. $\frac{1}{4}$ S 31 BT

6" Pine N 40 E 19.9 ft. $\frac{1}{4}$ S 31 BT

(No second tree north of line and so I scribed 9" Juniper as indicated.)

This corner is about 30 ft. south of solid rock outcropping.

North $\frac{1}{4}$ Corner, Section 31

Found original marked stone in mound. The original BT is burned off stub a foot or so high and exterior gone. Bearing and Distance check ok. to it and also to original line, 26" pine 224.4 ft. east of $\frac{1}{4}$ corner stone per original notes. (This line pine is bleazed windfall now.)

I scribed:

24" Pine N 26 E 54.5 ft. $\frac{1}{4}$ S 30 BT"

16" Pine S 64 W 78.0 ft. $\frac{1}{4}$ S 31 BT"

This corner is about 200 ft. west of old logging road running southerly down draw.

Northeast Corner Section 31

There is stone in mound about 50 ft. north of E-W log road. USFS tag on log road. I did not need this corner and did not check it against original notes.

H. C.
Taylor
1957