


CORNER RESTORATION



NW cor.
CORNER Sec. 1 TWP 14 S RANGE 30 E
ORIGINAL SURVEY BY: S.W. Lackland
CONTRACT NUMBER: 357
CONTRACT DATE: July 2, 1880



ORIGINAL DESCRIPTION: Intersect township boundary 41.23 chains west of established corner to Sections 35 & 36. At which point I set stone 18x12x6 in mound of stone for closing corner to Sections 1 & 12.

RESTORATION BY, STAMP AND DATE:

R.D. Bagett
J.L. Watson
K.J. Workman



RECEIVED AND
FILED

APR 25 1989

OFFICE OF COUNTY SURVEYOR
Robert D. Bagett
Agent

March 13, 1989

EVIDENCE FOUND:

This corner is lost due to road construction. I set the corner at single proportionate measure between the accepted monuments at the SW and SE corners of Section 35, T13S, R30E. The centerline stripe of County Road NO. 49 is 23 feet west of this monument.

SEE RECORD MAP OF SURVEY NO. 1071

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:


Show how trees are scribed and basis of bearings, including compass var.

MONUMENT MARKED

At the corner point: I set a 5/8"x30" iron pin, with attached 1-1/2" alum. cap driven flush with ground.

Cap marked as shown.

No corner accessories were taken.



A-21
See Remon Dated April 1971