

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

X-25

History of original corner establishment:

Corner was established by Deputies Banford Robb and Samuel W. Lackland in 1880, contract #357, Set: Stone 16"x10"x8" in a mound of stone.

Corner was monumented by the BLM in 1978 by proportion. See record field notes.

DIAGRAM

T14S
R30E R31E
1/4
S36 | S31

Description of corner evidence found:

BLM iron post with 3" brass cap firmly set 6" above road surface in a mound of stone. Stamped:

T14S
R30E R31E
1/4
S36 | S31
1978

BLM 9" Fir now 10" White Fir N72W--15.8' Healed blaze.
BLM 15' now 17" Juniper S87E--45.5' Scribing visible.

Description of monument and accessories | established to perpetuate the

original location of this corner:

Marked:


10" D-Fir S7W--39.3' Scribed 1/4 S36 BT with a 1" brass disk stamped PLS 896 nailed flush between the B and the T.

17" D-Fir N54 1/4 E--60.6' Scribed 1/4 S31 BT with a 1" brass disk stamped PLS 896 nailed flush between the B and the T.


Painted bands and blazes on all BT's red and nailed 54-9 and 54-3 signs to BT's as needed.

Set guard post North with 54-9 and 54-2 signs.

Declination 20.



Larry D. Bishop



EXPIRES 11-23-97

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 16 day of Aug, 1996
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)

See MDS 1422