

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. G-19

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T15S R31E
C1/4
.
S11
1988
PLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 26" in the ground.

From Which:

60d Nail driven in the East side of a 24" Pine Bears S 5⁰13'E., 18.52 ft.

60d Nail driven in the West side of a 26" Pine Bears N36⁰32'E., 6.68 ft.

Measurements to nails in trees taken with electronic tachemeter with angles turned from the survey control network.

Since the corner falls in the yard of the Guest Ranch (Resort) the trees are not blazed, scribed, painted or are there any signs used.

Note: while the position of this corner does not show any problems as concern the USFS, it indicates some boundary problems to the private owners, abutting the E-W Center of Section Line.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1988
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.

On: May 2, 1988
Refer to Map of Survey No. 1038

Office of Sherman County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 28 day of Mar, 1989
Robert D. Bays by _____
(COUNTY OFFICIAL) (DEPUTY)