


CORNER RESTORATION

S. $\frac{1}{4}$ Cor.
CORNER Sed. 13 TWP 15 S. RANGE 31E.

ORIGINAL SURVEY BY: Banford Robb

CONTRACT NUMBER: 357

CONTRACT DATE: July 2, 1880



ORIGINAL DESCRIPTION:

39.74-Set post for $\frac{1}{4}$ section corner from which,

A pine 18" dia. bears S40°W, 50 Lks. dist.

A pine 20" dia. bears N60°E, 102 Lks. dist.

RECEIVED AND
FILED

OCT 18 1972

JOHN LIVEIRA, County Clerk

RESTORATION BY, STAMP AND DATE:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

By

Deputy

ROBERT D. BAGETT
JULY 12, 1963
598

Sept. 27, 1972

EVIDENCE FOUND: None.

Set S. $\frac{1}{4}$ corner by Proportionate measure.

Survey No. 274.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set 1 $\frac{1}{2}$ "x30" galvanized iron pipe 20" in ground with brass cap marked
as shown, from which NEW BEARING TREES, MONUMENT MARKED

A 7" fir bears N13°W., 5.65 feet marked $\frac{1}{4}$ S13 CS BT

A 12" fir bears S47°E., 25.70 feet marked $\frac{1}{4}$ S24 CS BT

Measured horizontal dist. to blaze on BTs from
brass cap.

Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820

Comp. Var. 20°

