


CORNER RESTORATION

W $\frac{1}{4}$ Cor.
CORNER Sec. 19 TWP 15S RANGE 32E

ORIGINAL SURVEY BY: Bamford Robb

CONTRACT NUMBER: 357

CONTRACT DATE: July 2, 1880



ORIGINAL DESCRIPTION:

North between Secs. 19 and 24.

40.00 set post for $\frac{1}{4}$ cor. on bank of brook 3 lks. wide flowing N.E., from which:


A hemlock 10" in diam. bears S. 80° E., 12 lks. dist.

A pine 36" in diam. bears N. 30° W., 60 lks. dist.

RECEIVED AND
FILED

RESTORATION BY, STAMP AND DATE.

R. D. Bagett
W. Gentis



DEC 20 1976
John Liveira
JOHN LIVEIRA, County Clerk
By _____ Deputy

May 10, 1976

Grant County Surveyor

EVIDENCE FOUND:

No evidence of the original corner post was found. I established the $\frac{1}{4}$ corner at record distance from the remains of the original BTs.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point: Set a $1\frac{1}{2}$ "x30" iron pipe 24" in the ground, from which the ORIGINAL BEARING TREES:

A 22" hemlock stump bears N. 86° E. 7.9 ft. with bottom of axe blaze in top of stump, blaze visible, no scribing.
A 48" fir stump (rotten) bears N. 36° W., 39.6 ft. with no marks visible.

I scribe NEW BEARING TREES:

A 24" fir bears N. 85° W. 22.5 ft. mkd. $\frac{1}{4}$ S24CSBT.
An 18" fir bears S. 24° E. 65.0 ft. mkd. $\frac{1}{4}$ S19CSBT.

This corner falls in the creek in Road Gulch. I used a compass with a 20° East variation and a steel tape, measuring to face of BT blaze.

MONUMENT MARKED

