


CORNER RESTORATION

E 1/16 Cor.
CORNER Secs. 19 & 30 TWP 15S RANGE 32E

ORIGINAL SURVEY BY:

CONTRACT NUMBER: E 1/16 not previously established

CONTRACT DATE:



ORIGINAL DESCRIPTION:

E 1/16 not previously established.

RESTORATION BY, STAMP AND DATE:

R. D. Bagett
W. Gentis

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

May 6, 1976

Grant County Surveyor.

EVIDENCE FOUND:

Not applicable

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point: Set 5/8"x30" iron pin 26" in the ground for E 1/16 cor. between Secs. 19 and 30, from which I scribe NEW BT's:

An 8" fir brs. N. 52° W., 36.8 ft. dist. mkd. E1/16S19CSBT.
A 10" pine brs. S. 15° W. 28.6 ft. dist. mkd. E1/16S30CSBT.

I used a compass with 20° East variation and steel tape, measuring to face of BT blaze.

MONUMENT MARKED



On 6-9-79 I took a new bearing tree at the request of Mike Cosgrove who wanted to construct a house which would destroy the BT in Sec. 30. The new BT's as follows: from the corner point:
A Fir 11" diam bears S 87° W 86.6 ft., mkd E 1/16 S 30 CSBT.

RECEIVED AND
FILED

DEC 20 1976

JOHN LIVEIRA, County Clerk
By _____ Deputy