


CORNER RESTORATION

C $\frac{1}{4}$ Cor.
CORNER Sec. 29 TWP 15S RANGE 32E

ORIGINAL SURVEY BY:

CONTRACT NUMBER: C $\frac{1}{4}$ Corner not previously established

CONTRACT DATE:




ORIGINAL DESCRIPTION:


C $\frac{1}{4}$ Corner not previously established. Established C $\frac{1}{4}$ Cor. Section 29 at intersection of lines from opposite corresponding $\frac{1}{4}$ corners.

RESTORATION BY, STAMP AND DATE:

R. D. Bagett
W. Gentis



Robert D. Bagett



May 4, 1976

Grant County Surveyor

EVIDENCE FOUND:

Not applicable.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:


Show how trees are scribed and basis of bearings, including compass var.

Set a 1 $\frac{1}{2}$ "x30" iron pipe 26" in the ground with brass cap attached and marked as shown, from which I scribe
NEW BEARING TREES:

A 6" fir brs. N. 14° E., 7.6 ft. mkd. C $\frac{1}{4}$ S29CSBT.
A 20" fir brs. S. 60° W., 6.5 ft. mkd. C $\frac{1}{4}$ S29CSBT.

I used a compass with 20° East variation and steel tape measuring to face of BT blaze.

MONUMENT MARKED



RECEIVED AND
FILED

DEC 20 1976
John Liveira
JOHN LIVEIRA, County Clerk

By _____ Deputy

See map of survey No. 398.