


CORNER RESTORATION

Center East 1/16
CORNER Sec.29 TWP 15S RANGE 32E

ORIGINAL SURVEY BY:

CONTRACT NUMBER:

CONTRACT DATE:




ORIGINAL DESCRIPTION:


CE 1/16 corner not previously established.

RESTORATION BY, STAMP AND DATE:

R. D. Bagett
W. Gentis



Robert D. Bagett



May 4, 1976

Grant County Surveyor

EVIDENCE FOUND:

Not applicable

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:
Show how trees are scribed and basis of bearings, including compass var.

At the corner point: Drive 5/8"x30" iron pin 26" in the ground and surrounded same with a mound of stone, from which I scribe NEW BEARING TREES:

An 11" pine bears N. 78° E., 5.2 ft. mkd. CE1/16S29CSBT.
An 8" pine bears S. 26° W., 30.6 ft. mkd. CE1/16S29CSBT.

I used a compass with a 20° East variation and a steel tape measuring to the face of the bearing tree blaze.

MONUMENT MARKED



RECEIVED AND
FILED

DEC 20 1976
John Liveira
JOHN LIVEIRA, County Clerk

By _____ Deputy