


CORNER RESTORATION

N.W. Cor.
CORNER Sec. 35 TWP 15S., RANGE 32 E.
ORIGINAL SURVEY BY: Geo. Rigby
CONTRACT NUMBER: Group No. 215
CONTRACT DATE: April 19, 1939




ORIGINAL DESCRIPTION:
80.00 Set Iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, for cor. of
Secs. 26 and 35 only, with Brass cap mkd
From Which:
A pine, 10 ins. diam., brs. N. 7° 00' E., 65 lks. dist. mkd
T15SR32E S26 BT
A pine, 12 ins. diam., brs S. 20° 00' E., 7 lks. dist. mkd
T15SR32E S35 BT
S34 | T15S
S26
S35
R32E
1939

RESTORATION BY, STAMP AND DATE:
R. D. BAGETT
W. GENTIS
REGISTERED
PROFESSIONAL
LAND SURVEYOR
Robert D. Bagett
OREGON
JULY 12, 1993
ROBERT D. BAGETT
598
FEB. 1976 GRANT COUNTY SURVEYOR.

EVIDENCE FOUND:
Found 1939 GLO BRASS CAP
From which:
A 16" pine brs. S. 20° E., 7 lks dist. with scribing visible in partially healed blaze.
A 14" pine brs. N. 7° E., 65 lks dist. with scribing visible in partially healed blaze.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:
Show how trees are scribed and basis of bearings, including compass var.
Since I found this corner and the BTs to be in excellent shape, I did nothing on the ground to further perpetuate the position of this corner. I am filing this remonumentation sheet as an update on the condition of the corner.

MONUMENT MARKED



RECEIVED AND
FILED

See Map of Survey No. 398

NOV 29 1976

JOHN LIVEIRA, County Clerk
By *Barbara Lemon* Deputy