


CORNER RESTORATION

C.S. 1/16 Cor.
CORNER Sec. 34 TWP 15 S. RANGE 32 E.

ORIGINAL SURVEY BY:

CONTRACT NUMBER:

CONTRACT DATE:



ORIGINAL DESCRIPTION:

Corner not previously established.

RESTORATION BY, STAMP AND DATE:

R. D. BAGETT
W. GENTIS

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett
OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

FEB. 18, 1976

GRANT COUNTY SURVEYOR

EVIDENCE FOUND:

Established C.S. 1/16th corner

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At corner point: Drove 5/8" x 30" iron pin 28" in the ground.


MONUMENT MARKED

From which: NEW BTs.

A 16" Fir brs. S. 69° E., 34.7 ft. dist. mkd CS1/16 S34CSBT

A 15" Pine brs. N. 13° E., 27.0 ft. dist. mkd CS1/16 S34CSBT

Used compass with 20° E. Var. and steel tape, measuring to face of BT blaze.



RECEIVED AND
FILED

NOV 29 1976

See Map of Survey No. 398

JOHN LIVEIRA, County Clerk

By *Darlene Lemoria* Deputy

Y-15