


CORNER RESTORATION

CORNER: N1/4 Cor. Sec. 3 Twp. 16 S. Range 27 E., W.M.

ORIGINAL SURVEY BY: Samuel W. Lackland **CORNER**

CONTRACT NUMBER: 415 **NOT**

CONTRACT DATE: August 19, 1881 **PREVIOUSLY SET**



Subsequent surveys:

- ▶ Gary Oviatt & Wayne Rogers in 1975 under special instructions dated August 25, 1975, Survey/Group No. 882

ORIGINAL DESCRIPTION: CORNER NOT PREVIOUSLY SET

▶ 1975:

The point for the $\frac{1}{4}$ sec. cor. of sec. 3 only, T. 16 S. R. 27 E., is at midpoint on the N. bdy. of sec. 3.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 8 ins. in the ground, to solid rock, and in a mound of stone, 3 ft. base, to top, with brass cap mkd.

$\frac{1}{4}$ S 3
T 16 S R 27 E
1976

Corner is located 0.08 chs. north of a fence corner, fences extend S. 70° E. and S.

From this point, the standard $\frac{1}{4}$ sec. cor. of sec. 34, T. 15 S., R. 27 E., bears N. $89^{\circ} 30'$ E., 10.00 chs. dist., hereinbefore described.

RESTORATION BY, STAMP AND DATE:

Michael C. Springer, PLS

RECEIVED AND FILED
GRANT COUNTY SURVEYOR

DEC 3 2010

BY:



EXPIRES: 6/30/2012

November 30, 2010

Grant County Surveyor

EVIDENCE FOUND: None. No field visit was made for this Corner Restoration Report, it is prepared from record information. See Record Map of Survey No. 889 filed in the office of the Grant County Surveyor.