


CORNER RESTORATION

CORNER: S1/4 Cor. Sec. 34 Twp. 16 S. Range 27 E., W.M.

ORIGINAL SURVEY BY: Bamford Robb

CONTRACT NUMBER: 366

CONTRACT DATE: August 18, 1880



Subsequent surveys:
▶ Gary Oviatt & Wayne Rogers in 1975 under special instructions dated August 25, 1975, Survey/Group No. 882

ORIGINAL DESCRIPTION: Set post for 1/4 sec. cor with mound of stone from which a pine 4 ft. diam. bears N25 °W. 168 lks dist.

- ▶ 1975: Oviatt’s and Rogers’ field notes state: the 1/4 sec. cor. of secs. 3 and 34, determined at record bearing and distance from the original bearing tree: a ponderosa pine, 48 ins. diam., bears N.25 °W., 168 lks. dist., with scribe marks 1/4 S visible on opened blaze.
At the corner point Set an iron post, 28 ins. long, 2½ ins. diam., 18 ins. in the ground to solid rock, and in a mound of stone 3 ft. base, to top, with brass cap mkd.
From which
A ponderosa pine, 24 ins. daim. bears S.4¼°E., 147 lks dist., mkd. 1/4 S3 BT

RESTORATION BY, STAMP AND DATE:

Michael C. Springer, PLS

RECEIVED AND FILED
GRANT COUNTY SURVEYOR

OCT 28, 2010

BY: 



October 28, 2010

Grant County Surveyor

EVIDENCE FOUND: None. This Corner Restoration Report is prepared from record information.

RECORD MARKINGS ON BRASS CAP PER BLM FIELD NOTES

T16S R27E
1/4 $\frac{S34}{S3}$
T17S
1975