


CORNER RESTORATION

CORNER: SE Cor. Sec. 34 Twp. 16 S. Range 27 E., W.M.

ORIGINAL SURVEY BY: Bamford Robb

CONTRACT NUMBER: 366

CONTRACT DATE: August 18, 1880



Subsequent surveys:

- Gary Oviatt & Wayne Rogers in 1975 under special instructions dated August 25, 1975, Survey/Group No. 882

ORIGINAL DESCRIPTION: *At intersection of three long deep canyons set post with one pit and mound for cor to secs 34-35-2 & 3 from which a
Pine 10 in. diam. bears N80°E, 54 lks. dist.
Pine 30 in. diam. bears N18°W, 44 lks. dist.
Pine 14 in. diam. bears S30°W 64 lks. dist.*

- 1975: Oviatt's and Rogers' field notes state: *The cor. of secs. 2, 3, 34 and 35, determined at record bearing and distance from the remains of the original bearing trees: A sawed ponderosa pine stump 27 ins. diam., bears N.18° W., 44 lks. dist., with scribe marks T16 R27 BT visible on open double blaze.
At the corner point Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.*

From which new bearing trees:

A juniper, 14 ins. diam., bears N.45°E., 22 lks. dist., mkd. T16S R27E S35 BT

A juniper, 22 ins. diam., bears S.36¾°E., 75½ lks. dist., mkd. T17S R27E S2 BT

A juniper, 10 ins. diam., bears S.56½°W., 133 lks. dist., mkd. T17S R27E S3 BT


RESTORATION BY, STAMP AND DATE:

Michael C. Springer, PLS

RECEIVED AND FILED
GRANT COUNTY SURVEYOR

OCT 28, 2010

BY:



EXPIRES: 6/30/2012

October 28, 2010

Grant County Surveyor

EVIDENCE FOUND: None. This Corner Restoration Report is prepared from record information.

RECORD MARKINGS ON BRASS CAP PER BLM FIELD NOTES

T16S R27E
S34 | S35
S3 | S2
T17S
1975