


CORNER RESTORATION

CORNER: S1/4 Cor. Sec. 35 Twp. 16 S. Range 27 E., W.M.

ORIGINAL SURVEY BY: Bamford Robb

CONTRACT NUMBER: 366

CONTRACT DATE: August 18, 1880



Subsequent surveys:
► Gary Oviatt & Wayne Rogers in 1975 under special instructions
dated August 25, 1975, Survey/Group No. 882

ORIGINAL DESCRIPTION: Set stone 12x9x7 in mound of stone for 1/4 sec cor

- 1975: Oviatt’s and Rogers’ field notes state: *the 1/4 sec. cor. of sec. 2 and 35, monumented with the original basalt stone 12x9x7 ins., loosely set 3 ins. in the ground, mkd. 1/4 on N. face. At the corner point Set an iron post, 28 ins. long, 2½ ins. diam., 16 ins. in the ground to solid rock, and in a mound of stone 2 ft. base, to top, with brass cap mkd. From which*
A juniper, 8 ins. diam. bears N.44½°E., 69 lks dist., mkd. 1/4 S35 BT
A juniper, 10 ins. diam. bears S.62¾°E., 11½ lks. dist.,mkd. 1/4 S2 BT
Deposit corner stone alongside iron post.

RESTORATION BY, STAMP AND DATE:

Michael C. Springer, PLS

RECEIVED AND FILED
GRANT COUNTY SURVEYOR

OCT 18, 2010
BY:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 9, 2002
MICHAEL C. SPRINGER
#70918

EXPIRES: 6/30/2012

October 22, 2010

Grant County Surveyor

EVIDENCE FOUND: None. This Corner Restoration Report is prepared from record information.

RECORD MARKINGS ON BRASS CAP PER BLM FIELD NOTES

T16S R27E
1/4 S35
S2
T17S
1975