

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. C-11

History of original corner establishment:

None. Corner established this survey.

DIAGRAM
T16S R33½E
C1/4
S4
1993
PLS 2405

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/4" aluminum cap, stamped as shown on the DIAGRAM, 20" in the ground and raised a mound of stone around the monument.

From Which:

Lodgepole Pine, 10" dia., bears N52°14'E, 203.3 ft., scribed: C1/4 S4 BT
Lodgepole Pine, 10" dia., bears S03°56'W, 73.8 ft., scribed: C1/4 S4 BT

5/8"x30" rebar, set 28" in the ground, with yellow plastic cap marked PLS 2405, bears:

N54°47'W, 9.2 ft.
S55°52'E, 9.7 ft. (1 groove on rebar)

Measurements to BT's and rebar taken with an Electronic Tacheometer with bearings based on the survey control network. Set steel fence post with Land Survey Monument (54-9) sign 5' south of the monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 26, 1989
SUSAN E. NEWSTETTER
2405

This work was performed by:
Susan E. Newstetter PLS 2405
Witnessed by: Rick Saul and
Rick Pewonka
September 24, 1993
Refer to Grant Co. Survey No.: 1283

Office of Surveying County of Grant
State of OR I hereby certify that the within instrument was
filed in this office for record on the 21 day of Jan, 1994
Robert D. Bayett by _____
(COUNTY OFFICIAL) (DEPUTY)

C-11