

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. T-19

History of original corner establishment:

None. Corner established this survey.

DIAGRAM
T16S R33½E
C 1/4
•
S26
1993
PLS 2405

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, 26" in the ground.

From Which:

As references set 5/8"x30" rebars, with yellow plastic caps marked PLS 2405, 28 inches in the ground, at the following bearing and distance:

N48°44'W, 9.7 ft., no grooves on rebar
N44°12'E, 8.8 ft., 1 groove on rebar
S49°51'E, 10.3 ft., 2 grooves on rebar
S44°52'W, 9.8 ft., 3 grooves on rebar

Measurements to rebars taken with an Electronic Tacheometer with bearings based on the survey control network. Set steel fence post with Land Survey Monument (54-9) and Property Boundary (54-2) signs 5' south of the monument.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 26, 1989
SUSAN E. NEWSTETTER
2405

This work was performed by:
Susan E. Newstetter PLS 2405
Witnessed by: Rick Saul and
Rick Pewonka
October 6, 1993
Refer to Grant Co. Survey No.: 1311

Office of Sumner County of Grant
State of OR I hereby certify that the within instrument was
filed in this office for record on the 28 day of Mar, 1994
Robert D. Bayett by _____
(COUNTY OFFICIAL) (DEPUTY)