

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. W-19

History of original corner establishment:

None. Corner established this survey.

DIAGRAM
T16S R33½E
C
N1/16 | S35
C
1993
PLS 2405

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, 26" in the ground.

From Which:

As references set 5/8"x30" rebars, with yellow plastic caps marked PLS 2405, 28 inches in the ground, at the following bearing and distance:

N37°37'W, 9.6 ft., no grooves on rebar
S38°00'E, 9.9 ft., 1 groove on rebar

Measurements to rebars taken with an Electronic Tacheometer with bearings based on the survey control network. Set steel fence post with Land Survey Monument (54-9) and Property Boundary (54-2) signs 5' north of the monument.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

This work was performed by:
Susan E. Newstetter PLS 2405
Witnessed by: Rick Saul and
Rick Pewonka
October 6, 1993
Refer to Grant Co. Survey No.: 1311

OREGON
JULY 26, 1989
SUSAN E. NEWSTETTER
2405

Renewal Date: 12/31/94

Office of Sumner County of Grant
State of OR I hereby certify that the within instrument was
filed in this office for record on the 20 day of Mar, 1994
Robert D. Bayless by _____
(COUNTY OFFICIAL) (DEPUTY)

W-19