CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This corner was originally established by Aaron F. York in 1878 under contract #309. Set stone 12"x8"x6". Raised mound of stone at corner.

DIAGRAM

T8S R27E
1/4 S29|S28

Description of corner evidence found:

Stone 12"x8"x6" at West side of a collapsed mound of stone. No visible marks identified. No other stone for 150' in all directions.

Description of monument and accessories I established to perpetuate the original location of this corner:

T8S R27E
1/4
S29|S28
1992
LS 896

Set 2½"x 30" alum. pipe with a 2½" alum. cap 20" in ground in a mound of stone 2½' base to top. Stamped:

Buried original stone South and adjacent to the monument.

Marked:

10" Pine--S53W 40.8' Scribed 1/4 S29 BT.
10" Juniper--S67E 17.6' Scribed 1/4 S28 BT.
5/8" iron rod with red plastic cap stamped PLS 896--N70W 19.28'.
5/8" iron rod with red plastic cap stamped PLS 896--N5¼E 41.10'.
Nailed 54-9 and 54-3 signs to BT's, painted bands and blazes red and nailed a 1" brass disk stamped PLS 896 flush between the B and the T.
Set guard post N13E.
Dec. 20.

REGISTERED PROFESSIONAL LAND SURVEYOR

Larry D. Bishop

OREGON
JULY 11, 1989
LARRY D. BISHOP
896

Office of Dayton County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office for record on the 20 day of JAN, 1993
Kenneth D. Bazett by
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

1246
☆GPO—798-276

T-9