

No. 24 1/2 FOR Samuel Reynolds

TOWNSHIP 8 S

RANGE 31 E WILL. MER.

Chas F Patterson was notified by me Wm Curt appeared
 chains Began at SW cor Sec 36 T8R31 Ran S 89° 20' W
 40 00 The S 1/4 cor Sec 35 fall 8 links from S 1/4 corner Ran S 89° 20' W
 40 00 Set Temp Sec Corner Continued S 89° 20' W
 46 00 The S 1/4 cor Sec 34 ^{not setting} Proceeded to Temp Sec Corner and set it permanently marked properly and mound of rocks
 from SW corner Sec 35 as thus established ran N 10° E
 20 Set Temp 1/4
 40 The W 1/4 cor Sec 35 falling W 20 lks. proceeded to Temp 1/4 cor and set permanently marked 1/4 CS
 Then proceeded to NW corner Sec 36 T8R31 and ran N 30° E
 40 the E 1/4 cor Sec 26 missing Set Temp 1/4 cor continued
 39 64 the NE cor Sec 26 falling W 60 lks. back to Temp 1/4 corner corrected it, marked 1/4 CS and set well
 From 1/4 corner as thus established Ran S 89° 20' W
 80 60 W 1/4 corner missing
 Proceeded to SW cor Sec 26 which is in good condition Ran N 10° E
 80 NW corner Sec 26 missing back to Temp 1/4 cor and set it permanently and marked
 Proceeded to Temp centre of Sec 26 corrected, set, and marked 1/4 CS

July 20 1910

Costs Survey 3 days 1500

Measurements 3 " 1500

Mileage 800

Compiling Report 500

Recording 360

Redman 750

Apportionment 500

\$5910

Michael Spears County Surveyor