

Began at SW corner Sec 28 T8 R 31 Ran North on Random line
 40 1/4 corner missing
 80 did not find Sec corner
 120 1/4 corner miss
 160 did not find Sec corner
 200 1/4 corner miss
 240 did not find Sec corner
 280 1/4 corner miss
 320 did not find
 360 1/4 corner miss
 400 The NW corner Sec 4 T8 = SW corner Sec 33 T8 R 31 falling 140 the E

I then retraced carefully looking for traces of old line, found some blazes on first 1/2 mile in timber bearing approximately S 30° W from NW corner Sec 4 I took this course on South

until I found a mound of Rocks where the SW corner of Sec 4 should be. marks have faded I remarked proceeding South I found more blazes North of Creek and one Spruce South of creek these blazes bear S 10° W from SW corner Sec 4 instead of due South as in US field notes

I retraced on this course to a point where the SW corner of Sec 9 should be and at the corner of old fence lines found a pile of rocks nearly buried but no marked rock from the position of old fences corroborated by the measurements from North and from NW corner Sec 18 T8 R 31 I decide the Old corner to have been in this mound I marked another and set in mound of rocks for Corner Sec 16-17-20-4

From this corner I run due South along the old fence and at the point where the SW corner Sec 16 should be we found a mound of rocks nearly buried with one Rock setting up in centre unmarked. I remarked it for SW corner Sec 16 proceeding South another 1/2 mile we found the Old Gov corner (ie SW corner Sec 21)

The Bearings of this line show that the Government Survey was Run West of North from NW corner Sec 33 - SW corner Sec 16 then one mile due North then a curve to E making a great Bend in line

The location of this line forms a base to work from. it has long been known that the corners along this line were missing and from reports of land cruisers and private surveys it had been found that the line fences along this line were along ways West of where a true line should be from SW corner Sec 33 to the NW corner Sec 4 but the evidences found show that the Old fences were intended to be approximately on the old line as surveyed by the Gov

Costs were	6 days Survey	\$30.00
	" " Measure	\$30.00
	Compiling Report	5.00
	Apportionment	5.00
	Record	3.60
	Mileage	8.00
	Flagman	15.00
	Total	\$96.60

Survey began July 24 1910

Survey No 26 for Samuel Reynolds T8S R31E

began at SW corner of Sec 21 Ran East

20.00 set temp 1/4.
 80 corner of line fences corner testified to be at this point - Set a Rock in mound of Rocks North from this corner

40.00 1/4 corner miss did not establish (Application withdrawn) Hence W

20.00 did not establish the application withdrawn by Reynolds

proceed to temp 1/4 connected a marked established

20 Set and established 1/4 corner = centre SW 1/4 Sec 21 Hence W

20 the W 1/4 corner (ie the NW corner of the SW 1/4 x SW 1/4) fall S 5° E

also in this survey include the establishing of 1/4 corner between SW corner and W 1/4 corner Sec 27

Costs 1 day Survey & measure

Mileage

Compiling Report

Apportionment

Record

Flag

2.50
\$34.10

Changed Reynolds \$10.00

Dr Waller 6.00

Felix Johnson 6.00

and let rest of bill go

Aug 4th 1910