


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

A19



History of original corner establishment:
Page 2 of 2 Corner History continued:

Corner was maintained by Gary Langlitz,
on July 27, 1982. His record states:
No trace of the orig. corner post remains.
Found a 2 1/2" Galvanized Iron Pipe extending
8" above the ground, with brass cap attached,
marked: (as per corner diagram)

From Which: an original 6" Pine, now a 7" P. Pine
snag, with scribing "BT" visible on a previously opened
blaze, bears N66°W 33.0 feet, and an orig. 26" Fir, now
a 27" Douglas Fir snag, partially opened, scars visible, bears S38 1/2°E
21.1 feet. And BT's apparently established by the BLM: A 14" Douglas Fir
with scribing "1/4 S35 BT" visible on an unhealed single blaze, bears
N 5 1/2°W 11.3 feet; And a 14" Douglas Fir with scribing "1/4 S 2 BT"
visible on a single blaze bears S56°E 42.0 feet.

Description of corner evidence found:

Description of monument and accessories | established to perpetuate the
original location of this corner:

Sheet 2 of 2

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

RENEWS 12-31-94

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 7 day of May, 1994
Robert D. Boyer by _____
(COUNTY OFFICIAL) (DEPUTY)