

RECEIVED AND  
FILED

JUN 14 1973

JOHN LIVEIRA, County Clerk

By *Betty Lowery* Deputy


CORNER RESTORATION

CORNER N 1/4 cor.  
Sec. 32 TWP 7S RANGE 31E., W.M.

ORIGINAL SURVEY BY: Frank W. Campbell

CONTRACT NUMBER: 380

CONTRACT DATE: March 19, 1881



ORIGINAL DESCRIPTION:

S.89°00' West on a true line bet. secs. 29 and 32.  
 31.93 Creek 3 lks. wide runs NW.  
 31.98 Set a tamarack post for 1/4 sec. cor., from which a  
 Pine 48" dia. bears N.32°E., 22 lks.  
 Pine 40" dia bears S.23°E., 33 lks. dist.

RESTORATION BY, STAMP AND DATE:

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Robert D. Baggett*

OREGON  
JULY 12, 1963  
ROBERT D. BAGGETT  
598

May 5, 1973

County Surveyor

EVIDENCE FOUND:

Found a 3"x3" squared post scribed 1/4 on 3 sides wired to a 1/2"x60" iron pipe. the iron pipe was driven 50" in the ground, from which a stump hole bears N38°E 21 ft.  
 a stump hole bears S 39°E 24.4 ft.  
 A N-S fenceline bears East 2 ft.

I accept this position as the 1/4 corner.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point: Set a 1 1/2"x36" iron pipe 33" in the ground with brass cap marked as shown: from which NEW BEARING TREES: MONUMENT MARKED

A 12" tamarack bears S60°W., 20.4 feet, marked 1/4 S32 CS BT.

A 10" pine bears N52°W., 30.2 feet, marked 1/4 S29 CS BT.

Drove the found iron pipe west and alongside the brass capped monument.

Used compass with 20° East variation and steel tape measuring to the face of the blaze on the BTs.

Complete and File with Office of the Grant

County Surveyor, Grant County, Oregon,

Courthouse, Canyon City, Oregon 97820

