

**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**History of original corner establishment:**

Corner was established and monumented by Otis O. Gould, Surveyor, during a subdivision survey Group No. 179 dated July, 1937.

Set an iron post, 3 ft. long, 1 in. diam., 20 ins. in the ground to solid rock, and in a mound of stone to top, for 1/4 sec. cor., with brass cap marked (as shown in the diagram)

from which

- A fir 20 ins. diam. brs. N52°W, (11.2')17 lks. dist., marked 1/4 S7 BT
- A tamarack 36 ins. diam. brs. S30°W, (18.5')28 lks. dist., marked 1/4 S18 BT

**DIAGRAM**

T8S R36E

S 7  
1/4 ---  
S18

1937  
GLO

**Description of corner evidence found:**

3/4" pipe with a 2 1/2" brass cap standing 18" out of the ground. The monument managed to survive being in or very near to a logging skid road, but not much evidence of any rock mound. There is a good chance the monument was reset during or shortly after the logging operation.

24" White fir (18" Stump) (Bottom of Blaze Visible) (1937 BT) bears N42°W, 12.9 feet.

26" Western larch (24" Stump) (No Visible Marks) (1937 BT) bears S30° 30'W, 16.0 feet. It appears that the monument may have been moved about 1 1/2 feet to the SW during the logging.

**Description of monument and accessories I established to perpetuate the original location of this corner:**

Maintained the monument by making sure it was firmly set in the ground and built a new mound of rock to be 30" in diameter by 14" high around the monument, from which new BTs are:

12" White fir bears N79° 30'W, 82.0 feet scribed 1/4 S7 BT

9" White fir bears S7°E, 27.0 feet scribed 1/4 S18 BT

Attached BT and Attention signs to and painted a red band around each BT. Bearings were taken with a staff compass, using a declination of 18° 30'E, to the scribed blazes which were painted red. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground. Even though the corner monument may not be in its original location, it was not deemed necessary to reset the monument because of the relatively minor distance, there being no property affected by this corner, and the low property values.

Set a steel fence post 5 feet W of the corner with an Attention sign attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on August 7, 1985, I maintained the corner as herein described.

**FILED**

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 16 DAY OF Oct, 1985

*Robert D. Baggett Co. Sur.*

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Leland Lee Myers*

OREGON  
JULY 9, 1965  
LELAND LEE MYERS  
699