

Survey No. 1525 was used to subdivide the section. This survey corrects the position of the monumented CS1/16 corner shown on Survey No. 1530. Ties to the unaccepted monuments near the corner positions at the S1/4 corner, C1/4 corner, CS1/16 corner and the SE corner of Section 31 are shown and the true positions are monumented in this survey. The CN1/16 corner and the N1/16 corner are established and monumented as shown. This survey was performed in accordance with the 1973 BLM Manual of Surveying Instructions. The lines of the S1/2NE1/4 and the N1/2SE1/4 were staked for fencing.

Cornerstone Surveying, Inc.
233 S. Canyon Blvd.
John Day, OR 97845
(541)575-1813

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Jack L. Watson

OREGON
SEPTEMBER 19, 1995
JACK L. WATSON
2734
RENEWAL DATE: 6/30/2004

RECEIVED AND
FILED

SEP 17, 2002
OFFICE OF COUNTY SURVEYOR
Robert C. Spang
Attest: *Michael C. Spang*