

### **Description and Location of Control Points:**

- Pnt. 1: Control point "Ogilvie", NGS PID QC1049: see NGS data sheet QC1049 for description and location. Situated in Section 27, T.13S., R.31E., W.M., Grant County, Oregon.
- Pnt. 2: Control point "Prairie City N. Base Reset" NGS PID QC1048: see NGS data sheet QC1048 for description and location. Situated in Section 14, T.13S., R.33E., W.M., Grant County, Oregon.
- Pnt. 3: Is a 5/8" iron pin with attached yellow plastic cap marked "Thomas/Wright, Inc.. To reach this point, follow Hwy. 26 east from Prairie City to Hwy. 7 to Baker City. At 1.5 miles, turn left from Hwy. 7 onto Grant County Road 20 to Susanville. 0.4 miles downstream of milepost 3 on Middle Fork road (GC 20), directly in line with white Grant County right-of-way marker signs for "PC 137+66.86, 50 lt." the point is 6.4 feet left of the left edge of pavement in the gravel shoulder. Situated in Section 13, T.11S., R.34E., W.M., Grant County, Oregon.
- Pnt. 4: Is a 5/8" iron pin with attached yellow plastic cap marked "Thomas/Wright, Inc.. To reach this point, follow Hwy. 26 east from Prairie City to Hwy. 7 to Baker City. At 1.5 miles, turn left from Hwy. 7 onto Grant County Road 20 to Susanville. 365 feet along left shoulder of Middle Fork Road (GC 20) from a sign for Caribou Creek located downstream of milepost 4. The point is located 1.55 feet left of the left edge of pavement in the gravel shoulder. Situated in Section 12, T.11S., R.34E., W.M., Grant County, Oregon.
- Pnt. 5: Is a 5/8" iron pin with attached yellow plastic cap marked "Thomas/Wright, Inc.. To reach this point, follow Hwy. 26 east from John Day to Prairie City, turn right on Bridge St, continue for 0.4 mile to County Road No. 62, continue. 0.4 mile, east along County Road 62, 215 feet east of gray mailbox located at address 29226. The point is located 5 feet north of the north edge of pavement in the gravel shoulder. Situated in Section 11, T.13S., R.33E., W.M., Grant County, Oregon.
- Pnt. 6: Is a PK nail. To reach this point, follow Hwy. 26 east from John Day to Prairie City, turn right on Bridge St, continue for 0.4 mile to County Road No. 62, continue. 0.6 mile east along County Road 62, across from the black mailbox at address 29056 with the white fencing and gate. The point is on the north side of the road at the edge of pavement. Situated in Section 12, T.13S., R.33E., W.M., Grant County, Oregon.
- Pnt. 7: Control point "D 706", NGS PID PA0652: See NGS data sheet PA0652 for description and location. Situated in Section 6, T.19S., R.32E., W.M., Harney County, Oregon.