
BASIS OF BEARINGS

LAND PARTITION PLAT NO. 2006-14 AS SHOWN

## REFERENCES

RECORD MAP OF SURVEY NO.'S 245, 467, 580, 609, 613 763, 1034 & 1779

LAND PARTITION PLAT NO. 2006-14
GRANT COUNTY CORNER RESTORATION RECORDS
GLO AND BLM FIELD NOTES
DEED RECORD INSTRUMENT NO. 980111



## SCALE: 1'=200' SCALE: 1'=200' S1/2NE1/4 EASEMENT C1/4 COR. BERRYS CREEK NW1/4SE1/4 S30.00 NW1/4SE1/4

DETAIL

RECEIVED AND FILED
GRANT COUNTY SURVEYOR

JUL 1 2015

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 9, 2002
MICHAEL C. SPRINGER
#70918

EXPIRES: 6/30/2016

## NARRATIVE

THIS SURVEY WAS PERFORMED AT THE REQUEST OF GORDON LARSON. THE PURPOSE OF THIS SURVEY WAS TO MONUMENT THE PROPOSED PROPERTY LINE ADJUSTMENT SHOWN HEREON.

I SEARCHED AVAILABLE RECORDS PERTAINING TO THIS SURVEY AND FOUND THE FOLLOWING SURVEY RECORDS: THE SOUTH AND WEST LINES AND THE WEST HALF OF THE NORTH LINE OF SECTION 36 WERE ORIGINALLY SURVEYED BY BAMFORD ROBB, U.S. DEPUTY SURVEYOR FOR THE GLO, IN 1880 UNDER CONTRACT NO. 357. THE ORIGINAL SURVEY OF THE EAST LINE AND THE EAST HALF OF THE NORTH LINE OF SECTION 36 WAS CONDUCTED BY WILLIAM GIBB, U.S. DEPUTY SURVEYOR FOR THE GLO IN 1910 UNDER CONTRACT NO. 783.

IN 1939 THE RANGE LINE BETWEEN T.14S., R.31E. AND T.14S., R.32E. WAS RESURVEYED BY GEORGE F. RIGBY, CADASTRAL ENGINEER UNDER SPECIAL INSTRUCTIONS DATED MARCH 19, 1938 INCLUDED IN GROUP NO. 216 FOR THE GENERAL LAND OFFICE (GLO). DURING HIS SURVEY, MR. RIGBY FOUND THE MONUMENTS SET PREVIOUSLY BY WILLIAM GIBB TO BE OUT OF TOLERANCE. RIGBY UTILIZED THE MONUMENTS SET BY GIBB, BUT CALLS THEM OUT AS ANGLE POINTS IN THE RANGE LINE.

I ALSO FOUND THE FOLLOWING MAPS OF SURVEYS IN THE GRANT COUNTY SURVEYOR'S RECORDS: RECORD MAP OF SURVEY NO.'S 245, 467, 580, 609, 613, 763, 1034, 1779 AND LAND PARTITION PLAT NO. 2006-14. I ACCEPT THE FOUND MONUMENTS SHOWN HEREON FROM THE AFOREMENTIONED SURVEYS.

THE CORNER RESTORATION SHEET FOR THE S1/4 CORNER OF SECTION 36 STATES THAT A GRANT COUNTY SURVEYOR BRASS CAP WAS SET AT THAT POINT. WE FOUND A BRASS CAPPED MONUMENT AT THAT POSITION, BUT IT WAS NOT STAMPED WITH THE TYPICAL "GRANT COUNTY SURVEYOR" MARKINGS. THE MONUMENT IS IN THE RECORD POSITION AND HAS ALL THE OTHER PROPER DESIGNATIONS AND INFORMATION AND I ACCEPT IT AS THE 1/4 CORNER.

AFTER LOCATING THE CONTROLLING CORNERS, I SUBDIVIDED SECTION 36 WITH REFERENCE TO THE 2009 BLM MANUAL OF SURVEYING INSTRUCTIONS. I SET NEW MONUMENTS ALONG THE ADJUSTED PROPERTY LINE AT LOCATIONS APPROVED BY MR. LARSON AND ACCORDING TO THE EVIDENCE FOUND.

SEE RECORDS OF CORNER MONUMENTATION FILED IN THE OFFICE OF THE GRANT COUNTY SURVEYOR FOR MORE DETAILS ON THE CORNERS I SET AND THEIR ACCESSORIES.

## LEGEND

- FOUND 1½" GALV. IRON PIPE WITH ATTACHED GRANT COUNTY SURVEYOR BRASS CAP UNLESS OTHERWISE NOTED
- FOUND 1939 GLO BRASS CAP AS SHOWN
- FOUND 1978 BLM BRASS CAP FROM SURVEY NO. 613
- FOUND 5/8" IRON PIN NO CAP FROM SURVEY NO. 609
- FOUND 5/8" IRON PIN WITH ATTACHED YELLOW PLASTIC CAP MARKED BGA SURVEY MARKER
- SET 5/8"X30" IRON PIN WITH ATTACHED 1½" ALUMINUM CAP MARKED BMLS SURVEY MARKER AND WITH APPROPRIATE 1/16 CORNER DESIGNATIONS
- SET 5/8"X30" IRON PIN WITH ATTACHED 3½" ALUMINUM CAP MARKED BENCHMARK LAND SURVEYING AND WITH APPROPRIATE C1/4 CORNER DESIGNATION
- O SET 5/8"X30" IRON PIN WITH ATTACHED YELLOW PLASTIC CAP MARKED BENCHMARK SURVEYING
- G( ) ORIGINAL GLO RECORD BEARING AND DISTANCE
- ( ) RECORD BEARING AND DISTANCE FROM SURVEY NO. 609
- [ ] RECORD BEARING AND DISTANCE FROM SURVEY NO. 467
- 1[ ] RECORD BEARING AND DISTANCE FROM SURVEY NO. 613
- 2[ ] RECORD BEARING AND DISTANCE FROM SURVEY NO. 763
- 3[ ] RECORD BEARING AND DISTANCE FROM SURVEY NO. 580
- 4[ ] RECORD BEARING AND DISTANCE FROM SURVEY NO. 245
- 5[ ] RECORD BEARING AND DISTANCE FROM SURVEY NO. 1034
  6[ ] RECORD BEARING AND DISTANCE FROM SURVEY NO. 1779
- 7[ ] RECORD BEARING AND DISTANCE FROM PARTITION PLAT NO. 2006-14
- FOUND MONUMENT FROM RECORDED SURVEY NO.

---- PROPOSED PROPERTY LINE ADJUSTMENT

