

which Mr. Bernard stated was the 1/16 corner on the Township line.


A line from our set hub to this fence corner was marked with lath.

Mr. Bernard was advised there may be some variation in this 1/16 line.

Monuments found and set as well as measured angles, distances and calculated bearings are shown on the attached map of the Survey, which by reference is made a part of these notes.


I certify this work was done under my direct supervision.

Donald J. Branton




CHECKED AND APPROVED:

TENNESON ENGINEERING CORPORATION



By

  
Donald J. Branton, President

