

CW1/16 cor. Public Right of Way Deed Bk 111 Pg 151 N89'14'06"E 975.55 N89°14'06"E 435.45 336. 1346.27 Parcel Parcel 5.00 Ac. 12.37 Ac. East 435.05 Parcel 5.00 Ac. (336.00) -336.00easement Bk 125 Pg 190 N10°E 40.0 easement, Bk 121 Pg 312. N89°40'23"E 336.03 --434.69 -S89°40'23"W SW1/16 cor. Initial Point 1"=200' Scale Point being 2441.12' south and 975.62' east of the NW corner of Section 1.

1"=500' Scale

LAND PARTITION PLAT NO. 97-34 SITUATED IN THE SW1/4 OF SECTION 1

T14S, R30É, W.M. Grant County, Oregon

November 29, 1997

LEGEND

- Found 1½" galv. iron pipe with attached Grant
- Found 5/8" iron pin with attached aluminum cap.
- Set 5/8" x 30" iron pin with attached red plastic cap marked CORNERSTONE SURVEYING, INC.
- Set 5/8"x 30" iron pin with attached 2" glum. cap marked CORNERSTONE SURVEYING, INC., with additional marks as shown.
- X-X Fence Line
- GLO record bearing and distance.
- Record bearing and distance, Survey No. 1071.
- Found monument, see record map of survey number shown in box.

I find no record or existance of a Geodetic Control Monument within 1/2 mile of this land partition.

do hereby certify that this is a true and exact copy of Land Partition No. 1-34

I do hereby certify that this is a true and exact copy of Land Partition No. 1


SURVEYOR'S CERTIFICATE

I, Jack L. Watson, Professional Land Surveyor, registered in the State of Oregon, hereby certify that I have correctly surveyed and marked with proper monuments, the parcels of this land partition situated in the NW1/4SW1/4 of Section 1, T14S, R30E, W.M., Grant County, Oregon,

Beginning at a 5/8" iron pin which I designate to be the Initial Point of this Land Partition, said point being 2441.12 feet south and 975.62 feet east of the NW corner of Section 1; thence S89°40°23"W, 967.18 feet to the easterly right of way of County Road No. 49; thence N00°02'30"W, along the easterly right of way of County Road No. 49, 999.60 feet to the north line of the S1/2N1/2NW1/4SW1/4 of Section 1; thence N89'14'06"E, along the north line of the S1/2N1/2NW1/4SW1/4 of Section 1, 975.55 feet; thence S00'25'50"W, 1007.13 feet to the point of beginning.

This partition contains 22.37 acres, more or less.

CORNERSTONE SURVEYING. INC. 233 S. Canyon Blvd. John Day, Óregon 97845 (541) 575-1813



APPROVALS

All ad valorem and special assessments due pursuant to law have been assessed and collected.

I do bereby certify that this plat was received on the 20 day of Exempton, 1997 at 2:00 o'clock.

M., and recorded as Land Partition Plat No. 21-31

Kothy Mchunn

RECEIVED AND FILED

DEC 2 3 1997

OFFICE OF COUNTY SHRYEYOR

DECLARATION

Know all people by these presents that Tom M. Gregg and Joyce M. Gregg, husband and wife, do hereby declare we are the owners of the lands described in the Surveyor's Certificate, and that we have caused the same to be partitioned into parcels in accordance with the provisions of ORS Chapter 92 as shown hereon.

SAID PARCELS ARE SUBJECT TO THE FOLLOWING:

1) Rights of the public in streets and roads.
2) A private utilities easement, including the terms and provisions thereof, 15 feet in width, to California—Pacific Utilities Company, dated June 17, 1976, recorded June 30, 1976, in Book 115, Page 6, deed records of Grant County.


3) A private access easement, including the terms and provisions thereof, 20 feet in width, dated June 27, 1979, recorded July 6, 1979, in Book 121, Page 312, deed records of Grant

4) A private easement, including the terms and provisions thereof, 30 feet in width, to C.P. National Corp., dated May 18, 1981, recorded August 11, 1981, in Book 125, Page 190, deeds of

Jan H Gregg

ACKNOWLEDGEMENT

STATE OF OREGON } SS



NARRATIVE

This survey was performed at the request of Chuck Church. The purpose of this survey was to partition the property described in Deed Instrument No. 972305, into 3 parcels.

After searching the available records pertaining to this survey, I found that Section 1 was subdivided during Survey No. 1071. I found all the controlling corners of Section 1, set during Survey No. 1071, in good condition except the monument at the W1/4 corner of Section 1 which has been destroyed by county road maintenance. I found the references and re-established the position of the W1/4 corner of Section 1 from them. I further subdivided Section 1 as called for in the deed. I set the parcel division lines at locations approved by Mr. Church, as shown hereon.

This survey was performed with a Topcon GTS-4 total station, with a closed loop random traverse.