


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

DIAGRAM

Corner was established by Bamford Robb, US Deputy Surveyor, during the original survey Joint Contract No. 357 dated July, 1880.



Set Post for cor to secs 1, 12, 6 and 7 with pits and mound as per instruction.

1986
PLS 699

Description of corner evidence found:

Corner location falls at the edge of an old railroad grade and private access road. No evidence of the original corner was found.

No bearing trees were previously established.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2"x30" aluminum pipe with 3 1/4" aluminum cap, marked as shown in the diagram, 26" in the ground, at single proportionate measurement from adjacent found corners. Built a mound of rock & earth to be 30" in diameter by 4" high around the monument on the road east fill slope.

No new bearing trees set because no trees are available.

1"x30" galv. pipe with 2 1/2" alum. cap Reference Monument bears N50°E, 7.5 feet marked RM 7.5' 1986 PLS 699.

1"x30" galv. pipe with 2 1/2" alum. cap Reference Monument on west side of road bears N47°W, 23.2 feet marked RM 23.2' 1986 PLS 699.

Set a steel fence post 5 feet N of the corner with an Attention sign attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on May 29, 1986, I monumented the corner as herein described.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 9, 1965
LELAND LEE MYERS
699

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 20 DAY OF June, 1986

Robert D. Baggett
Grant County Surveyor