

History of 1974 BLM Remonumentation

The $\frac{1}{4}$ sec. cor. sec. 24 only, on the E. bdy. of T. 7 S., R. 35 E., determined at record distance from the remains of the original bearing trees:

A root hole, bears S. 20° W., 17 lks. dist., with a down and decayed lodgepole pine alongside, 16 ins. diam., with scribe marks $\frac{1}{4}$ S BT visible on open double blaze. (Record, S. 60° W.)

A lodgepole pine, 16 ins. diam., bears N. 40° W., 12 lks. dist., with scribe marks $\frac{1}{4}$ visible on partially healed double blaze. (Record, S. 40° E.)

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 7 S
R 35 E | R $35\frac{1}{2}$ E
 $\frac{1}{4}$ S 24 |
1974

from which new bearing trees

A lodgepole pine, 13 ins. diam., bears S. 50° W., 97 lks. dist., mkd. $\frac{1}{4}$ S24 BT.

A lodgepole pine, 8 ins. diam., bears N. 49° W., 151 lks. dist., mkd. $\frac{1}{4}$ S24 BT.